

INVENTARIZACE STROMŮ

P.Č.	TAXON	VP	VŠ (m)	Š. KO (m)	TL. KM (cm)	OBVOD (cm)	TL.PAŘ. (cm)	VS (1-5)	VIT.	ZDR. STAV	SAD. HOD.	POZNÁMKA	PĚSTEBNÍ OPATŘENÍ	NÁROČNOST (1-3)	NALÉHAVOST
1	Salix fragilis	S	10	13	90x3	285x3	220	5	3	2-3	4	ok v 1m	ODS, stavba		
2	Rhus typhina	S	3	4	15	43	20	4	0	0	3	ok v 0,6m	ODS, stavba		
3	Prunus domestica	S	4,5	6	23,15	72,52	38	4	2	1-2	4	ok v 1m	ODS, stavba		
4	Salix fragilis	SS	4,5	3	8	28	12	2	0	0	3	ok v 0,6m			
5	Alnus glutinosa	SS	9	8	5x17,34,4x10	5x50,84,4x30	120	3-4	1	1	3	vrostlá v hrázi, hnízdo v koruně	ODS, stavba		
6	Alnus glutinosa	SS	10	8	16x16	16x55	180	3-4	1	1	3	vrostlá v hrázi	ODS, stavba		
7	Alnus glutinosa	SS	14	10	3x44,75,26	3x130,173,78	160	4	1	1-2	3		ODS, stavba		
8	Alnus glutinosa	SS	9	4,5	17	53	28	3	0	0	3		ODS, stavba		
9	Alnus glutinosa	SS	9	5	19,18	54	48	3	0	1	3		ODS, stavba		
10	Salix fragilis	SS	9	12	80	252	130	5	2-3	3	4-5		ODS, stavba		
11	Salix fragilis	SS	9	8	85	275	120	5	3	3	5	padlý do vody	ODS, stavba		
12	Robinia pseudoacacia	S	11	10	80	270	110	5	3	3	5	houbová infekce kmene s dutinou, havarijní stav, s nárůstem u paty kmene	ODS, zdravotní		
13	Salix fragilis	S	8	5	45	145	60	4	2-3	2-3	4	poraněný kmen, na dožití			